

RECALL SAFETY NOTICE

2021 & 2022 SCHWINN VOADOR AND KETTLE VALLEY EBIKES

AFFECTED BICYCLES

These models were only sold in Australia 14 January 2021 and 20 May 2022.



VOADOR — MEN'S FRAME STYLE

S7528SMAUS	Size: 40 small	GREY
S7528MDAUS	Size: 47.5 medium	GREY
S7528LGAUS	Size: 53 large	GREY



VOADOR — WOMEN'S FRAME STYLE

S7529SMAUS	Size: 40 small	TEAL
S7529MDAUS	Size: 47.5 medium	TEAL



VOADOR — STEP THRU FRAME STYLE

SCS7519AUS	Size: one size	BLACK
------------	----------------	-------

ISSUE

Some disc brake rotor mounting bolts may be missing Loctite thread retaining compound and/or have the wrong bolt head.

HAZARD

If these bolts become loose enough, they may hit the fork or frame, which may fracture the fork or frame, or instantly stop the front wheel and cause the rider to fall, with risk of serious injury or death.

WHAT TO DO

Consumers should stop riding these bikes and take them to an authorised Schwinn retailer for replacement of all disc brake rotor attachment bolts at no charge. The retailer will also place a small green sticker on the rotors to mark that the bolts have been replaced.

CONTACT DETAILS

Consumers can contact PSI Cycling by email at service@psicycling.com.au or by phone at 03 8327 8080.

We apologise for this inconvenience and thank you for your patience.

Sincerely,
The Schwinn and PSI Teams

